



University of
**Southern
Queensland**

F A C I L I T I E S M A N A G E M E N T

Service Interruption – Springfield Campus B Block Lifts

As you may be aware, both lifts in B Block were out of service this morning. One lift has since been returned to service. The other will remain out of service pending replacement of the unit's motherboard. This may take some weeks.

The out-of-service lift is also scheduled for complete replacement as soon as possible, noting that lead times for this equipment is 6-9 months.

Your patience during this interruption is appreciated and we apologise for any inconvenience caused.

For further information, please contact FMHelpDesk@unisq.edu.au on 4631 2627. For after hours, please contact Campus Safety and Security on 4631 2871.

We invite you to stay up-to-date with service interruptions via our [Facilities Management](#) Notices information page.

The University of Southern Queensland acknowledges the traditional custodians of the lands and waterways where the University is located. Further, we acknowledge the cultural diversity of Aboriginal and Torres Strait Islander peoples and pay respect to Elders past, present and future.



© University of Southern Queensland 2023. A member of the Regional Universities Network.
CRICOS: QLD 00244B, NSW 02225M | TEQSA: PRV12081